

BHUSD - WEEK AT A GLANCE - JANUARY 23, 2015 - MEASURE E IN ACTION - HORACE MANN



Basement formwork and steel



Image from workzone time lapse camera



Footing work. Note the grey "slurry" poured behind the waterproof membrane to mitigate the rain damage



Progress view